Risk Assessment for Saturator Services - Emergency Maintenance



			Analysis Inherent Risk		t Risk		Analysis Residual Risk		al Risk]		Analysis Target Risk			
Risk Number	Description of Risk [Cause/Event/Consequence]	Risk Owner	Likelihood	Impact	Inherent Risk [Before Controls]	Current Controls	Control Owner	Likelihood	Impact	Residual Risk [After Controls]	Proposed / Further Controls	Control Owner	Likelihood	Impact	Target Risk [Further Controls Implemented]
						1. Spill kit to minimise any spillage located in service vehicle	Service Engineer		1 2	2 2	spill kits located adjacent to plant on site	Site			
1	water contamination as a result of the spillage of brine	AM	2	3	6	2. Correct operating procedures communicated to operative to minimise potential for spill	Service Engineer	1					1	1	1
						 Plant designed to reduce potential spillage (max limit alarms, double skin tanks, etc.) 	AM								
	significant [immobilising] accident to lone working operative	AM	2	3	6	 Operator always to report to site supervisor upon arrival, and to log in / out of site 	Service Engineer								
2						Regular phone communication with head office advising of position	Service Engineer	1	3	3					
						 Adhesion to safe working practices as outlined in method statement 	Service Engineer								
						1. correct usage of appropriate PPE	Service Engineer		1						
3	operative contact with chemicals resulting in skin irritation / eye irritation / sickness through ingress	h AM	2	2	4	Adhesion to safe working practices as outlined in method statement	Service Engineer	2 1		2					
						 First Aid Kit available on site / in service vehicle stocked with appropriate remedies and eye wash 	Service Engineer		_	_					
						4. COSHH present for all chemicals	Service Engineer								
4	spillage of salt resulting in water / land	AM	3	2	6	1. Telehandler operator sufficiently trained to minimise spillages	Site	2	2 1	2	redesign of plant to enable greater loading area (using alternative loading methods or loading baffles)	AM	1	1	1
	contamination					2. removal of spilled salt post-event	Site								
						1. Use of MEWP, by trained employees, where site dictates	Service Engineer				redesign plant enabling zero working at height for routine maintenance			1	1
5	operative injury sustained whilst working at	AM	2	3	6	Work at height always carried out with a harness and restraining lanyard	Service Engineer	2	1	2		AM	1		
	height					 Ladders to be used when approved and when dictated by nature of requirement (ie infrequent use for short periods of time). Permit to use by senior management to be signed in advance of tasks. 	Service Engineer								
	physical danger to operative from additional site activities	e AM	3	2	6	 Correct use of PPE (high visibility clothing and safety boots especially) 	Service Engineer	2 1							
						Ensure site operatives are aware of service engineers presence through initial site meeting	Service Engineer								
6						 Use of traffic cones to section off workplace where necessary - client to provide. 	Service Engineer		1	2					
						 Use of site floodlights to increase visibility in darker winter months 	site								

Revision Date : Review Date :

Risk Assessment for Saturator Services - Emergency Maintenance



hood Impact Controls
Implemented]
2 2
2 2
2 2
L

Risk Matrix

probable	likely to occur each year	3	3	6	9
possible	likely to occur in a 10 year period	2	2	4	6
remote	remote not likely to occur in a 10 year period			2	3
ESTIMATION	DESCRIPTION		1	2	3
	Likelihood		LOW	MEDIUM	HIGH

Created By	Andrew Manson		Position	Technical Manager
Signed	A	L L	Date	28/10/2016

Approved By	Angus Craig	Ailia	Position	Commercial Director
Signed		Hyrang	Date	28/10/2016

Revision Date : Review Date : 28/10/2016 28/10/2017